

LaMotte Insta-Test® Test Strips

LaMotte offers a convenient, economical way to perform spot checks for several water quality factors. LaMotte test strips are a great way to monitor water without having to use reagents or field kits. Strips are available for the factors below... and more are in the works!



TEST STRIP FACTORS & SPECIFICATIONS

Single Factors

| Test Factor | Order Code | Range (ppm) | # of Tests | Values (ppm) |
|-----------------------|------------|----------------------|------------|--|
| Alkalinity | 2997 | 0-180 | 50 | 0, 40, 80, 120, 180 |
| Ammonia | 3023-G | 0-60 NH ₃ | 25 | 0, 0.5, 1.0, 3.0, 6.0 |
| Chlorine Dioxide | 3002 | 0-500 | 50 | 0, 10, 25, 50, 100, 250, 500 |
| Chlorine Dioxide LR | 2999LR | 0-10 | 50 | 0, 0.25, 0.5, 1, 3, 10 |
| Chlorine | 4250-BJ | 10-200 | 100 | 10, 50, 100, 200 |
| Chlorine LR | 2963LR-G | 0-10 | 25 | 0, 0.25, 0.5, 1, 3, 10 |
| Chlorine Total | 2979 | 0-5 | 50 | 0, 0.5, 1, 3, 5 |
| Chlorine Free HR | 3031 | 0-800 | 50 | 0, 50, 100, 250, 500, 800 |
| Chlorine Free & Total | 3027-G | .5-10 | 25 | 0.5, 1, 3, 5, 10 |
| Copper | 2991-G | 0-3 | 25 | 0, 0.3, 0.6, 1, 3 |
| Hardness LR | 2981 | 0-180 | 50 | 0, 30, 60, 120, 180 |
| Nitrate | 3012-G | 0-200 | 25 | 0, 10, 30, 60, 120, 200 |
| pH Wide Range | 2974 | 4-10 (pH) | 50 | 4, 5, 6, 7, 8, 9, 10 |
| Peracetic Acid HR | 3000HR | 0-1000 | 50 | 0, 50, 100, 250, 500, 1000 |
| Peracetic Acid | 3000 | 0-160 | 50 | 0, 10, 20, 50, 85, 160 |
| Peracetic Acid LR | 3000 | 0-160 | 50 | 0, 10, 20, 40, 60, 85, 160 |
| Peroxide | 2984 | 0-90 | 25 | 0, 15, 30, 50, 90 |
| Peroxide LR | 2984LR | 0-50 | 25 | 0, 1, 3, 10, 30, 50 |
| Sodium Chloride | 2998-12 | 1500-5000 | 120 | 1500, 2000, 2500, 3000, 3500, 4000, 5000 |

Multi-Factor

| Test Factor | Order Code | Range (ppm) | # of Tests | Values (ppm) |
|---|------------|------------------------|------------|----------------------|
| Total Chlorine, pH, Total Hardness & Iron | 2992 | Chlorine, Total, 0-10 | 25 | 0, 0.5, 1, 3, 5, 10 |
| | | pH, 4-10 | 25 | 4, 5, 6, 7, 8, 9, 10 |
| | | Hardness, Total, 0-450 | 25 | 0, 50, 100, 200, 450 |
| | | Iron, 0-5 | 25 | 0, 0.3, 0.5, 1, 3, 5 |
| Copper & Iron | 2994 | Copper, 0-3 | 25 | 0, 0.3, 0.6, 1, 3 |
| | | Iron, 0-5 | 25 | 0, 0.3, 0.5, 1, 3, 5 |
| pH Wide Range & Total Chlorine | 2987-G-12 | pH, 4-10 | 25 | 4, 5, 6, 7, 8, 9, 10 |
| | | Total Chlorine | 25 | 0, 0.5, 1, 3, 5, 10 |
| Nitrate & Nitrite | 2996 | Nitrate, 0-50 | 50 | 0, 5, 10, 25, 50 |
| | | Nitrite, 0-10 | 50 | 0, 0.5, 1, 5, 10 |

CALL GEOTECH TODAY (800) 833-7958

Geotech Environmental Equipment, Inc.

2650 East 40th Avenue • Denver, Colorado 80205

(303) 320-4764 • FAX (303) 322-7242

email: sales@geotechenv.com • website: www.geotechenv.com